

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director $\begin{array}{c} {\rm JON~M.~HUNTSMAN,~JR.} \\ {\rm \it Governor} \end{array}$

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

OGM Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0070041
Inspection Type:	COMPLETE
Inspection Date:	Friday, September 30, 2005
Start Date/Time:	9/30/2005 10:00:00 AM
End Date/Time:	9/30/2005 1:00:00 PM
Last Inspection:	Tuesday, August 30, 2005

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, 60's

InspectionID Report Number: 758

Accepted by: pgrubaug 10/14/2005

Permitee: WEST RIDGE RESOURCES
Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 1077, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages Mi

Total Permitted	4,382.55	
Total Disturbed	29.06	
Phase I		
Phase II		
Phase III		

Mineral Ownership Types of Operations

✓ Federal	✓ Underground
✓ State	Surface
County	Loadout
Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Pending Division Order: Division Order DO00A-7, Extension granted until May 2004. The Division received a response to Division Order DO-00A-7 on June 3, 2004. The Division Order was sent back to the permittee with deficiencies. The Division met with the permittee on November 29, 2004 and discussed the deficiencies. The Division is scheduled to finish the review by October 31, 2005.

Inspector's	Signature
-------------	-----------

Date

Tuesday, October 11, 2005

Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070041 Inspection Type: COMPLETE

Inspection Date: Friday, September 30, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.8	a Roads: Construction, Maintenance, Surfacing	✓			
16.	o Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0070041
Inspection Type: COMPLETE

Inspection Date: Friday, September 30, 2005 Page 3 of 3

2. Signs and Markers

The identification sign was inspected and complied with the R645 Coal Rules.

3. Topsoil

The topsoil pile has been re-disturbed and seeded as required in the experimental practices portion of the Mining and Reclamation Plan.

4.a Hydrologic Balance: Diversions

The diversions were inspected and would function as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were inspected by the permittee for the third quarter. No hazardous conditions were written in the report. I inspected the sediment ponds and found no hazardous conditions. Sediment pond upper cell did contain a small amount of water.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences were performing as designed.

4.d Hydrologic Balance: Water Monitoring

The permittee did conduct the third quarter water monitoring and entered the information into the Electronic Data System.

4.e Hydrologic Balance: Effluent Limitations

8. Noncoal Waste

The area was generally clean of non coal waste material.

18. Support Facilities, Utility Installations

No new construction has been conducted since the last inspection.

21. Bonding and Insurance

The mine permit will expire on April 1, 2009. This document is signed by both parties. The bond is \$2,117,000 and is by Federal Insurance Co.